

## Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection: 10-29-2020

3. Drainage District Name or Number: 1

4. Location of Damage or Complaint:

(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

NONE

6. Description of Damage (attach additional sheets if needed):

NONE

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

The owners I talked to were  
all OK with the water flowing

8. Inspector(s):

Print Name:

Richard M. Sobiestki

Signature:

Richard M. Sobiestki

## Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection: 10-29-2020

3. Drainage District Name or Number:

4. Location of Damage or Complaint:  
2 Twp

(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

None

6. Description of Damage (attach additional sheets if needed):

Note noted! Ditch in good shape - water flow very low  
only water entering ditch is from collection pump - all drain  
tile flow has ceased (W2291)

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

None Required - unless MR Eckert wants to extend  
ditch system to east end north to City I.

8. Inspector(s):

Print Name: Steven Foust

Signature: 

# Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection:

10-29-2020  
3. Drainage District Name or Number:

3 Three  
4. Location of Damage or Complaint:

(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

None!

6. Description of Damage (attach additional sheets if needed):

Ditch is in excellent condition! only slope cave was seen 200' east of City "U" on south side. At this point ditch widened to 30' plus and fail spot just changed side slope to the correct slope of 2:1. Most of this ditch has a 1:1 when it should be 2:1 or 2.5:1 slope for sandy soils.

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

Name - The side cave mentioned above is at a part where ditch is very wide, area does not effect flow.

8. Inspector(s):

Print Name: Steven Forest

Signature: 

## Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection: 10/29/2020

3. Drainage District Name or Number: 4

4. Location of Damage or Complaint:  
(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

NONE

6. Description of Damage (attach additional sheets if needed):

NONE

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

NONE

8. Inspector(s):

Print Name:

Richard M Sobieski

Signature:

Richard M Sobieski

## Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection: 10/29/20

3. Drainage District Name or Number: # 5

4. Location of Damage or Complaint:

(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

*None*

6. Description of Damage (attach additional sheets if needed):

*None*

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

*Ditch looked good, no complaints  
Small flow of water in center of ditch  
Could be mowed 1-2 times/year when dry*

8. Inspector(s):

Print Name: *Pat Krueger* *Todd Morris*

Signature: \_\_\_\_\_ *Todd Morris* \_\_\_\_\_

# Green Lake County's Inspection Report

1. Type of Inspection (check all that apply)  Annual  Major Storm  Site

2. Date of Inspection: 10/29/20

3. Drainage District Name or Number: Seneca-Warren

4. Location of Damage or Complaint:

(Attach USDA Farm Service Agency aerial photo with site identified in red)

5. Name of person(s) making complaint or accompanying the inspection:

~~Alf~~ Lavern Alf was present during inspection on his property.  
Paul Kujawa - called to complain of hunters jumping ditch bank to trespass.

6. Description of Damage (attach additional sheets if needed):

Took some elevations of ditch bottom at Alf's property & other sections.  
There is a buildup of sediment in west culvert on South Rd.  
Concern of Willow Tree at corner of Alf & DNR property in Corridor.  
Ditch bottom about 1.1' - 1.5' of sediment from original design.  
- May need to look culvert elevations in ditch.

7. Repairs Proposed or Action to be Taken by Board (attach additional sheets if needed):

Remove 1 ft of sediment from south Rd to approximately  
station 310+00.

8. Inspector(s):

Print Name: Todd Morris

Pat Krueger

Signature: Todd Morris

\_\_\_\_\_